

REPAIRABLE

REORDER FROM:
AVIATION BUSINESS SYSTEMS
725 North Memorial Parkway
HUNTSVILLE, ALABAMA 35801
1-800-633-2950

OWNER: Falcon Charter

Beacon Tail Grimes
UNIT NAME MFG. NAME

40-0127-1 8494
PART # MODEL or TYPE

TRACE-ABILITY
W4308 Tail 2/10/2020 9962
REMOVED FROM DATE WORK ORDER #

WORK TO BE DONE: will not repair

Wk. Ord. # _____ DATE _____

FAA Certificate No. XOFR185J

FALCON EXECUTIVE AVIATION, INC.

4766 E. FALCON DR.
MESA, AZ 85215
(480) 832-0704