

065-0040-00-R

KS 273 TRIM

TSD CS& DOCS ENV CAT
MAX DC INPUT MV SA.7
KING RAD

P/N 065 0040 -00

S/N 1309

TWO

BENDIX / KING
CRS 3333
IDENTIFICATION NO.
A 22427
DATE 6-22-89

SERVICEABLE

32-07
RAYTHEON AEROSPACE
2300 HORIZON DRIVE
FORT WORTH, TEXAS 76177
FAA CRS R29R0290

MAINTENANCE RELEASE

The aircraft, airframe, engine, propeller or appliance identified herein was repaired and inspected per current Federal regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair and inspection are on file at this repair station under

WORK ORDER 1-1369

INSPECTOR Kennard 11/13/01



Part # or Model 065-0040-00-R04

Nomenclature KS 273

Serial Number 1309

Total Since New _____

Time Since Overhaul _____

Cycles Since New _____

Cycles Since Overhaul _____

Repairs accomplished Visually Inspected.

Removed in serviceable condition A/c 21062582

Technician R. Lewis

Code 9D ATA 27-40-03

Date 11-13-01

065-0040-00-R

KS 273 TRIM SERVO

P/N 065-0040-00

TSO CS: D0136 ENV CAT BAJAAAXXXXXX

S/N 1309

MAX DC INPUT - 4V 5A, 28V 5A

WT. 2.2 LBS.

KING RADIO CORP.

TRIM
SERVO