

INPUT CONNECTORS UTILIZE  
POLARIZING KEYS - DO NOT USE  
EXCESSIVE ENGAGEMENT FORCE

WARRANTY  
VOID IF  
PROKEN



MOD	●	●	●	●	●	●	●	●	●	31	32	33	34
7	8	9	10							35	36	37	38
11	12	13	14							39	40	41	42
15	16	17	18							43	44	45	46
19	20	21	22							47	48	49	50
23	24	25	26							51	52	53	54
27	28	29	30							A	B	C	D
										E	F	G	H

**ELECTRONIC FLIGHT DISPLAY**  
TYPE NO. EPD-74 TSO C6c, CS2a, C40b  
DO-160A ENV CAT. /A2C1/B/PKS/XXXXXX/A/BZ/AZ  
WT 4.9 LB S/N 218  
COLLINS PN 622-6197-002  
Collins Avionics Division, Rockwell International  
Cedar Rapids, IA 52498 USA/Mtd Melbourne, FL



MAR 28 1984  
11/11/84