



REPAIRABLE

OWNER: Falcon charter

Beacon Tail Grimes _____
UNIT NAME MFG. NAME MODEL or TYPE

40-0127-1 _____ 8494
PART # SERIAL #

TRACE-ABILITY W4308 Tail _____ _____
REMOVED FROM DATE WORK ORDER #

WORK TO BE DONE: will not repair

Wk. Ord. # _____ _____ _____
DATE

FAA Certificate No. XOFR185J

FALCON EXECUTIVE AVIATION, INC.
 4766 E. FALCON DR.
 MESA, AZ 85215
 (480) 832-0704

REORDER FROM:
 AVIATION BUSINESS SYSTEMS
 725 North Memorial Parkway
 HUNTSVILLE, ALABAMA 35801
 1-800-633-2950