

BFGoodrich Aerospace
Component Overhaul & Repair
817 Dessau Rd., Austin, TX 78753-9710 (512) 251-3441
FAA Repair Station No. UZ2R232
CASTLEBERRY AERCOR Simmonds
Precision PSO

KA118 DEMODULATOR
P/N071-1095 01 SER/NO 2903
DO 138 ENV CAT BAJAAAXXXXXX
TSO C9c WT. 0.2lbs.
KING KING RADIO CORP. MODS
OLATHE, KANSAS U.S.A.

1	2	3	4
5	6	7	8

I-069

KA 118 S/N 2903

SERVICEABLE

RAYTHEON AEROSPACE
2300 HORIZON DRIVE
FORT WORTH, TEXAS 76177
FAA CRS R29R0290

MAINTENANCE RELEASE

The aircraft, airframe, engine, propeller or appliance identified herein was repaired and inspected per current Federal regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair and inspection are on file at this repair station under

WORK ORDER 001713

INSPECTOR Ken Waddell 11/15/01

MASS INSP
FAA CRS
01
AVIONICS

Part # or Model 071-1015-

Nomenclature KA118 DEMODULATOR

Serial Number 2903

Total Since New _____

Time Since Overhaul _____

Cycles Since New _____

Cycles Since Overhaul _____

Repairs accomplished INSP. KADRON AS GOOD

CONDITION - REMOVED FROM U12 0600078

Technician Ken Sisse

Code 14 ATA 34-10-00

Date _____

FORM RASSOO11

SERVICEABLE

BROWARD AVIONICS SERVICES, INC.

1575 W. COMMERCIAL BLVD., FT. LAUDERDALE FL. 33309 (305) 491-3170/776-
THE APPLIANCE IDENTIFIED BELOW WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION F.A.A. # SD4R514M

MODEL KA118 SN 2903 A/C H-1

PN 071-1095-01

WO 34023 DESC DEMODULATOR

CUST JDC

9-29-94 TECH A. Ambrose

BY B/C

INSP
97
INSP.

REPAIRED AT BANYAN AIR SERVICE, FT. LAUDERDALE EXECUTIVE AIRPORT