

100-364217-9 ANNUNCIATOR FAULT DETECTION SYSTEM

Beech Aircraft Corporation
Wichita, Kansas 67201

P/N 100-364217-9 QTY. 1
NAME P.C. Board S/N 642-A-78
DISTR. Indiana Beach GR 108588
A/C SERIAL _____ W/C NO. _____

WARRANTY ☐ R50#
REPAIR ☒ 46805
EXCHANGE ☐
DATE 11-1-78

RETURNED
CUSTOMER
PROPERTY

52-34221

WORK ORDER/MAINTENANCE RELEASE

BEECH AIRCRAFT CORPORATION, WICHITA, KANSAS, 67201, USA

PART NAME P.C.B. MODULE ASSY. PART NO. 100-364217-9

MAKE BEECH AIRCRAFT MODEL 200 S/N 642-A-78

THIS PART WAS: ☒ REPAIRED, ☐ REBUILT TO ZERO TIME,
☐ OVERHAULED, ☒ FUNCTIONALLY TESTED, ☐ ALTERED
AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS
OF THE FAA AND IS APPROVED FOR RETURN TO SERVICE.
PERTINENT DETAILS OF THE WORK ACCOMPLISHED ARE ON FILE
AT THIS REPAIR STATION UNDER W.O./R.S.O. NO. R50-46805

Larry R. Longle
AUTHORIZED SIGNATURE

10-30-78

DATE

☐ C.R.S.334

☐ C.R.S.334A

☒ M.M.F.3345

Pending
CERTIFICATE NO.

Form No. 78-37066