

4.5 V
.10 A

J0953

← EMBRAER DATA 28-NOV-2015
P/N 170-00635-403 N/A
NºSERIE 0000875903 INSP

REPAIRABLE

Myrtle Airline Services, Inc.
1114 Airdrome Ave.
Myrtle Beach, SC 29577

COMPONENT/PART WINDSHIELD

WIPER-SWITCH

P/N 170-00635-403

S/N 0000875903

MFG EMB

A/C/ENG/COMP# _____

DATE 15 MAR 2021

W.O.# 100303

(IF REQUIRED)

REASON FOR REMOVAL AND/OR

DAMAGE NOTED TROUBLESHOOTING

INITIATED BY MK 7030

MASI M-005

CRS #6MYR388D

REV. 0