

DO-178A
LEVEL=2

SOFTWARE MODS				
1	2	3	4	5
6	7	8	9	10

THIS LRU CAN BE REPLACED WITH AN LRU OF THE SAME MOD STATUS, OR HIGHER NUMBER SOFTWARE MOD STATUS.

GNS-XLS FMS
TSO-C115b
TSO-C129
CLASS A1 B1 C1

17960-0102-0103

WT
LBS 5.10

S/N 3260

HARDWARE MODS			
1	2	3	4
5	6	7	8
9	10	11	12
13	14	15	16
17	18	19	20

THIS LRU CAN BE REPLACED WITH AN LRU HAVING THE SAME SET OF HARDWARE MODS. ADDITIONAL MODS ARE ACCEPTABLE.


Honeywell International, Inc.
Olathe, KS. USA CAGE 22373

BATTERY CHANGED
(JUL-2013)



LAMBDA 
ADVANCED ANALOG

52467
7942A
+5/±15V OUTPUT
246-018017-01 B
S/N D/C

 9833316 9839

 FUJITSU
BRUSHLESS
DC FAN
109P0424H302
DC 4V 0.15A
G100D0195A
SANYODENKI
MADE IN JAPAN

HT
119

103

**CAUTION**
CONTENTS SUBJECT TO
DAMAGE BY STATIC
ELECTRICITY
DO NOT OPEN
EXCEPT AT APPROVED
STATIC-FREE WORK STATION



**DUNCAN
AVIATION**
Duncan Aviation West
3410 W. Mathis St.
Lincoln, Nebraska 68524
800.LOANERS • 402.475.2611
Fax: 402.479.4213
www.DuncanAviation.aero
CRS#JGVR194F WO# 2BNTA

