

TELESCOPIC DUCT

P/N 3035-700

DATE NOV 07

F 1976
A T

S/N 1018

INSPECTION

R 01-15

-LHC F9588

A

DUNCAN
AVIATION



Repairable

Work Order Number 9AZQA

Squawk Number 1-1

Part Name TELESCOPIC TUBE

Part Number 5035-700

Serial Number 1018

Removed By DUCAN

Reg. Number N/A

Model N/A

AC Serial Number N/A

Customer WEST STAR AVIATION

Reason Removed

RETURNED AS IS

DUNCAN AVIATION-LNK

CRS#JGVR194F

Date 11/21/22