

DITTS

Collins

860E-5



REPAIRABLE TAG

Jetran LLC.
1449 Airpark
Horseshoe Bay Tx. 78657

Customer Name: _____ Aircraft S/N. _____

Aircraft Reg. _____

Part Name: TRANSUBVIN DIE

P/N: 622-2921-006

S/N: 2578484

Aircraft TAT: _____ Aircraft TAC: _____

Reason for Removal/notes: _____

Mechanic: _____ A & P #: _____

Date: _____

AERO SKY AIRCRAFT MAINTENANCE
2030 First Ave., Hangar 4
San Antonio International Airport
San Antonio, Texas 78216
FAA CRS KQ7R556N / EASA 145.6281

WORK ORDER

AIRCRAFT
NUMBER:

NS297A

DR/TASK
CARD

DATE
REMOVED

Puc

NOMENCLATURE

DME

REMOVED
BY

DISCREPANCY

QC

PN 622-2921-006

SN 14453

QC REJECT

✓

PART I.D. TAG

FORM 6

QC ACCEPT

MOD DIST MEASURE EQPT FCC DATA 860E-5
TYPE NO. 860E-5 FAA TSO C66a
DO-160 ENV CAT. /A2D2/A/J/XXXXXXXXAAAAA
WT **15.8** LB S/N **14453**
COLLINS PN 622-2921- **006**
Collins Avionics Divisions/Rockwell International
Cedar Rapids, Iowa 52498 USA

2
4 5 6
9
10 11 12

13
17
20
24
26 27

ACD
482

ing
A T