

PIUS

P  
Air  
R

S  
ling  
om



628-8682-003  
REV Y

MOD			ATTITUDE HEADING COMPUTER			22	23	24			
1	2	3	TYPE NO. AHC-85E			25	26	27			
4	5	6	DO-160A ENV CAT. /A2F2/AJEXXXXXA/BZ/AZ/AZ/			28	29	30			
7	8	9	27.5 V DC 26 V 400 Hz			31	32	33			
10	11	12	WT	14.2	LB	S/N	LOHHC	34	35	36	
13	14	15	COLLINS PN 622-9336-			400	A	B	C		
16	17	18	Collins General Aviation Division/Rockwell Collins, Inc.						D	E	F
19	20	21	Cedar Rapids, IA 52499 USA/Mfg Melbourne, FL						G	H	J

CRS WTXR173J

# REPAIRABLE PART

796 Heritage Way  
Grand Junction, CO 81506-8643  
Phone: 970-243-7500  
Fax: 970-683-4846

Work Order Number: 56976	
Squawk Number: 16.27	
Customer / P.O. # N/A	
Part Name: AHC	
Part Number: 622-9336-400	
Serial Number: 10MHC	
TSN N/A	CSN N/A
Removed By: CD	Date: 21 DEC 02
N Number: NS27DS	
Model: AHC-85E	
AC Serial Number: 214	
AC Total Time: N/A	
Engine S/N: N/A	
Engine TSN N/A	TSO N/A
Engine CSN N/A	CSO N/A
Date Installed:	
Reason Removed: Attitude and heading failed	

TRANSPORT REQUIRES  
USE OF AN  
APPROVED CONTAINER

## CAUTION

DELICATE  
AIRCRAFT  
SENSOR



SPECIAL HANDLING  
AND PACKAGING  
REQUIRED