

MCN 1691

MOD INFO

SB

SIL

SB1

SB2

**COURSE INDICATOR**

TYPE NO. 331A-6R    FAA TSO C6c, C52a  
26 V AC 400 Hz 8 VA 5 V AC/DC 0.7 A

WT **5.1** LB    SER NO. **164**



COLLINS PN 792-6356-**002**

Collins Avionics Division/Rockwell International  
Cedar Rapids, Iowa 52406 USA

TIL REV D

IJ2

IJ1



**TRIUMPH INSTRUMENTS & AVIONICS**

425 Round Rock West Drive  
Suite 105  
Round Rock, TX 78681

866/532-2844  
512/218-1900

FUNCTIONAL TEST     REPAIR  
 OVERHAUL             FAR 43 APP.-E PAR(B)  
 S/N 164            CAL TO \_\_\_\_\_  
W/O 154642          DATE 12/07/05

**FAA No. J7DR707N**

**CAUTION**

DO NOT VOID WARRANTY.  
SERVICE ONLY IN AUTHORIZED  
INSTRUMENT SHOPS OR