


CAUTION
ANTENNA CALIBRATION REQUIRED.
FAILURE TO CAL MAY RESULT IN
BEARING ERROR AND/OR SYSTEM
FAILURE. CALL FIELD SERVICE AT
1-800-253-9525.



SKYWATCH® HP P/N: 805-11900-001
TRC899 S/N: 81084
FCC ID: PMY TRC899 TSO C118 TSO C147 CLASS A DO-178B LEVEL D
DO-160 ENV. CAT. [F2X]BAB[SBM]XXXXXXXXBABA[RR]L[XXXX]XXA
SW VERSION: 10 11 12 13 14 15 16 17 18 19 20 21
MODS: A B C D E F G H I J K L
Wt: 9.00 lbs.
(4.08 kg.)
L-3 Communications Avionics Systems, Inc. Grand Rapids, Michigan, USA





J1
INTERCONNECT



POWER



J7
TEST



J12
MEMORY CARD



SKYWATCH® HP
TRC899

P/N: 805-11900-001

S/N: 81084

FCC ID: PMY TRC899 TSO C118 TSO C147 CLASS A DO-178B LEVEL D
DO-160D ENV.CAT.(F2X)BAB[SBM]XXXXXXXXZBABA[RR]L[XXXX]XXA

SW VERSION:

1.0	1.1	1.2	1.3	1.4	1.5	1.6	1.7	1.8	1.9	2.0	2.1
☒	☒	☒	☒	☒	☒	☒	☒	☐	☐	☐	☐
A	B	C	D	E	F	G	H	I	J	K	L

Wt: 9.00 lbs.
(4.08 kg.)

MODS:

☒	☒	☒	☐	☐	☐	☐	☐	☐	☐	☐	☐
-------------------------------------	-------------------------------------	-------------------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------

L-3 Communications Avionics Systems, Inc. Grand Rapids, Michigan, USA

