

TURN COORDINATOR

2 MIN. TURN

TSO C3b

WEIGHT 1.6 LBS.


PART NO. 9000

SER. NO. 4845

UNITED INSTRUMENTS, INC.

WICHITA, KANSAS

U.S. PATENTS 4149418, 4161884, 4222278



CODE N. 1

DATE 1/88

MADE IN JAPAN

32-10
32-10

84011



IDENTIFICATION

ALLIANCE AVIATION OPERATIONS CENTER
2300 HORIZON DRIVE
FORT WORTH, TEXAS 76177
FAA CRS R29R0290

This tag is to identify a part removed from an aircraft, propeller or component thereof and shall be attached to the part until it is to be reinstalled or other task.

Quantity 1 EA
Part # or Model 9000
Nomenclature TURN CORP.
Serial Number 4845
Removed from N# 61DW
Return to A/C Yes No
Reason for Removal SYS. UPGRADE



Technician BOB G 9029
Code 9A ATA 27-00-00
Date 7/2/12 Work Order 2177