




SOFTWARE PART NUMBER:  
P15066



SOFTWARE VERSION:



**AirCell**

**P/N: P13989**

FAA/PMA

SEE AIRCELL INSTALLATION  
ELIGIBILITY LIST 290001

THIS PRODUCT IS PROTECTED UNDER  
VARIOUS UNITED STATES AND FOREIGN  
PATENTS AND PATENT APPLICATIONS

**DO-160F ENVIRONMENTAL  
CATEGORIES**

[F2W]BAB[S(LY)]EYFXFZ[B1]  
BX[AC]RRM[XXE1X]XXAX

**Rev: J**

**S/N: 1398911368**



# TEAR DOWN REPAIR REPORT

FAA Certified Repair Station #X8CR828N - EASA Certified 145.5595

**Item No.:** P13989 **Date Received:** 5/18/2021 12:00:00 AM  
**Customer PO No.:** N328LN RMR FORM **Serial No.:** 1398911368  
**Description:** Assembly, Top, ATG 4000, ABS-BA **RMA No.:** RMA36250

## Receiving Inspection:

rec as rev J minor scratches on case

## Customer Description:

Solid red status light

## Description of Repair:

Unit was rec. at rev. J. unit has some scratches

complaint verified, unit has solid red status light, completed software upgrade and unit continues to boot cycle

the processor has failed and needs replaced, upgrade to current rev \_AA

customer request to send back "as-is"

## Parts Repaired or Replaced:

Product Code	Quantity	Description	Lot # / Serial #
JBECERRA	1	Labor	
P13989	1	Assembly, Top, ATG 4000, ABS-BA	

## Repaired By:

**Inspected By:** GOGO\GTODD

## Tested By:

**Date Completed:** 5/19/2021 12:00:00 AM

This/these Unit(s) has/have been tested in accordance with the appropriate Gogo Business Aviation Acceptance Test Procedure (ATP) and is/are approved for return to service.