



70898ASSY130-364054- 1

REF DES PREFIX-

S/N 672 B 99

8256

305




JAN 30 1988

AC POWER MONITOR

KEY PINS 10 & 46

PIN 1



RAYTHEON AIRCRAFT SERVICES, INC. LA
5280 N. WARREN DRIVE
COLUMBUS, IN 47203

812-379-1132

REPAIRABLE PART Repair Station No. ML2D009L WORK ORDER

Date 1/14/05 for Arvin Meador # 17471/1

Mfr. Raytheon

Component A320 A/C Power Miniature PC Board

P/N Model 180 364054-1 Serial No. 672 B99

Condition of part, or repair needed, # 2 Inverter "Fail" light

Intermittent illumination, ~~#2~~ Previous work done

2 Inverter Replaced 2 times, Inverter PIC cards

Swapped NO change