



LEDEX INC.
VANDALIA, OHIO U.S.A.

OPER. VOLTAGE
28 V.D.C.

SELECTOR SWITCH
PART NO. 172934-001

ET
B33
I1

FALCON JET CORPORATION
LITTLE ROCK DIVISION
CRS YL1R642K

ADAMS FIELD
P. O. Box 967 - Little Rock, Ark. 72203

SERVICEABLE PARTS TAG

Part Number	172934-001	Part Ser. No.	13774
Part Name	Locket Sew Surtall		
For Aircraft Make & Model	F50	Aircraft Ser. No.	050
Aircraft Owner		Aircraft Reg. No.	95886
Disposition (Shop, etc.)			
Reason for Removal	o/c 7000 D		
Removed By	<i>E. Lamb</i>	Date	10-15-91
Installed By		Date	
		Insp.	
		Aircraft Reg. No.	

SERVICEABLE

FQC 39

1. APPROVING CIVIL AVIATION AUTHORITY/COUNTRY: FAA / UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 243822	
4. Organization Name and Address: CONSOLIDATED AIRCRAFT SUPPLY CO. INC. (631) 891-7700 800-422-6300 59 RATNOR AVENUE, HONKONKOMA, NEW YORK 11779 FAX: (631) 891-7706					
5. Work Order/Contract/Invoice Number: FAA#GIIR167K					
6. Item: 1 Description: Relay Part Number: 172934-001 Quantity: 1 Serial Number: FT0629 Status/Work: Inspected					
7. Remarks: THIS UNIT WAS MANUFACTURED FUNCTIONALLY TESTED IN ACCORDANCE WITH MANUFACTURER'S CURRENT MANUAL. THE WORK PERFORMED IS DETAILED ON THE ATTACHED INSPECTION REPORT. THIS UNIT IS BEING SHIPPED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145. ORIGINAL NUMBER IS 172934-001					
10. Specifies the items identified above were manufactured in conformity to: 14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return To Service <input type="checkbox"/> Other Regulation Specified in Block 12					
11. <input type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.					
12. Authorized Signature: WATSON 13a. Date: 12/10/86					
13. Name (typed or printed): WATSON 13b. Date: 12/10/86					
14. Approved Signature: WATSON 14a. Name (typed or printed): WATSON 14b. Date: 12/10/86					
14c. Approval Certificate No: GIIR167K 14d. Date Issued: 12/10/86					
15. User/Installer Responsibilities: WATSON					
It is intended to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. When the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. The user/installer must ensure that the work performed is in accordance with the national regulations of the country specified in Block 1. The user/installer must ensure that the work performed is in accordance with the national regulations of the country specified in Block 1. The user/installer must ensure that the work performed is in accordance with the national regulations of the country specified in Block 1.					