

RTS  
378EH

ERA HELICOPTERS, INC.  
Return to Service Record

PART NAME Sleeve

PART NO. 206-001-141-001

SERIAL NO. N/A

MAINTENANCE REPORT

CHECK BLOCK  
OVERHAULED  REPAIRED  BENCH CHECKED

T.T. UNK T.C.

T.S.O. UNK C.S.O.

DATE 9-28-87

BRIEF REPORT OF WORK ACCOMPLISHED:

Removed from 378EH  
when dual controls  
were installed.

OVERHAULED  
REPAIRED OR BC BY Ralph Combs 407541234 <sup>AP</sup>  
MECHANIC

INSTALLATION RECORD

AIRCRAFT NUMBER \_\_\_\_\_ DATE \_\_\_\_\_

AIRCRAFT TOTAL TIME \_\_\_\_\_

POSITION ON AIRCRAFT \_\_\_\_\_

INSTALLED BY \_\_\_\_\_

UNIT REMOVED SERIAL NO. \_\_\_\_\_

REASON REMOVED \_\_\_\_\_