

1. Approving National Aviation Authority/Country FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 15H1A0001092001	
4. Organization Name and Address: Duncan Aviation/Lincoln Airport/Lincoln, NE 68524			5. Work Order/Contract/Invoice Number: 15H1A		12. Status/Work: Inspected
6. Item: 1	7. Description: STOP HOUSING ASSY	8. Part Number: 232-20242-7	9. Eligibility: N/A	10. Quantity: 1	11. Serial/Batch Number: NA

13. Remarks:

Customer: DUNCAN AVIATION

Inspected part removed serviceable from thrust reverser P/N 6608231-6 S/N 0334 and determined part to be airworthy.
 Inspected IAW the Learjet (Formerly Aeronca) Thrust Reverser Maintenance Manual 78-30-00, Rev 14, dated January 15, 1995.

Duncan Aviation certifies that the work specified in Blocks 12 and 13 was performed I.A.W. EASA Implementation Rule part 145 approval, and with respect to that work, the aircraft component is considered ready for release to service under EASA approval number EASA.145.4392. Certificate Number JGVR194F.
 All EASA/FAA Airworthiness Directives are the responsibility of the installer.
 No current U.S. Airworthiness Directives apply.

This document constitutes a signed copy of the work order for return to service

14. Certifies the data is correct:
- Approved design
 - Non-approved design

Other regulations specified in Block 13
 If, in accordance with Block 13, the work identified in Block 12 is accomplished in accordance with Title 14, part 43 and in respect to that work, the items are

Signature: **Gregory A Witt**
 Title: **Director of Quality**
 Date: **Oct 25, 2013**

21. Approval/Certificate No.: **JGVR194F**
 23. Date Issued: **Oct 25, 2013**

NSN-0052-00-012-0000
 Page 1 of 1