



Warranty

820-671

BENDIX-8047



SERIAL NO.

122A

SWACO P/N
27-19118-9

Warranty

MAINTENANCE RELEASE

COMPONENT AC volts, Prop pump
~~Piston Heat~~ SERIAL NO 122A
 PART/MODEL NO 27-19118-9

Overhaul Repair Functional Test

The Aircraft Appliance identified above was overhauled, repaired, or functional tested as per block above in accordance with current Federal Aviation Administration Regulations and is approved for return to service. Details of this component are on file at this agency under:

Work Order # 708144 Date 12-1-97

Authorized Signature Ralph L. Posey Form No. F150

ATA

NEVITT AIRCRAFT INC. — SERVICEABLE PARTS TAG

<input type="checkbox"/>	Name <u>TRI-meter</u>	PN <u>27-19118-9</u> ^{SOP} <u>82C-671</u>
<input type="checkbox"/>	SN <u>122</u>	TSO <u>ONK</u> Date Rec. <u>12-1-97</u>
	Vendor <u>MESS</u>	W.O. <u>—</u>
	Shelf Life <u>—</u>	Insp. <u>STH</u>
	<input type="checkbox"/> New <input type="checkbox"/> O/H <input type="checkbox"/> Repaired <input checked="" type="checkbox"/> Bench ck <input type="checkbox"/> Removed Time Rem. <u>—</u>	
	Remarks <u>Serviceable - bench ck good</u>	
A/C	TAT	TC
Reason for Removal		
Position	Off SN	Mech.
Date of Installation		

ATA