

WOODWARD

®

PROPELLER SYNCHRONIZER

TYPE

NUMBER

FAA-PMA
SWITCH MUST BE OFF FOR
TAKEOFF AND LANDING

WOODWARD GOVERNOR COMPANY

ROCKFORD, ILL. - FT. COLLINS, COLO.

PROTECTED UNDER ONE OR MORE OF THE FOLLOWING
U.S. PATENTS:

3,206,640 3,206,641 3,367,110

CONTROL BOX NO.

213433

SERIAL NO.

1199770 U-W

MAINTENANCE RELEASE TAG

Manufacturer **WOODWARD GOVERNOR COMPANY**

Model No. 213433

Serial No. 1199770 U-W

The component identified above has been repaired/overhauled in accordance with Federal Aviation Regulations and found airworthy for return to service. Pertinent details are on file under W.G. order No. 653286-R

WOODWARD GOVERNOR COMPANY

ROCKFORD, ILLINOIS

FAA Approved Repair Station #3781

(signed) *Bob Swenson*

Date 8/10/65

724-78A

11-38