

Collins

VIR-432


MOD

RCVR, VOR/LOC/GS/MB

TYPE NO VIR-432 FAA TSO C40,C350,C340,C350
DO-160A CLASS E D A
ENV CAT /A2E1/B/JY/EXXXXXZ/B2/AZA
WT 4.5 LB S/N 2184
FCC ID A1L9UQ P/N 622-7194
Rockwell International Corporation
Cedar Rapids, IA 52499 USA Mfg Melbourne, FL

(13/14/15)
(16/17/18)
(19/20/21)
(22/23/24)
A B C

#86



MNE-CJU Maintenance Center(B03)

SERVICEABLE

MOLIT Certificate Number

☒ 2004-AMO-A01 (M&E)☐ 2004-AMO-S02 (ASD)

Instance Number		Manufacturer		Preservation Maintenance		
				Complete Date	Due date	Inspector
				YYYY-MM-DD	YYYY-MM-DD	
Description						
VHF NAV RECEIVER						
Part Number		Storage Limit Control		YYYY-MM-DD	YYYY-MM-DD	
622-7194-201				YYYY-MM-DD	YYYY-MM-DD	
Serial Number	Quantity	Part Attribute		YYYY-MM-DD	YYYY-MM-DD	
2134	- 1 -					
Service Date	TSO/CSO	☐ Life Limited Parts		Hard Time Control Part Date Only		
YYYY-MM-DD		☐ ESDS		Manufacture Date	HYD Test Date	Restoration Date
2020-07-10				YYYY-MM-DD	YYYY-MM-DD	YYYY-MM-DD
Technician	RTS/Inspector	☐ Hard Time Control				
JS오정기 2004065		☐ CMP Chk Required				
PO/Work Order No	Status/Work	Remarks				
Serviceable Removed From						
A/C Type(or NHA P/N)		A/C No(or NHA S/N)				
CTN-560		HL7501				
Position						
#1						