

Collins

 **Rockwell** Avionics
Collins

WICHITA SERVICE CENTER
2051 Airport Road
Wichita, KS 67209-1949
PHONE: (316) 946-4808
FAX: (316) 942-3843

VHF-22A

MOD
6
7
12


TRANSCEIVER, VHF COMM
TYPE NO. VHF-22A FAA TSO C38c, C37c
DO-160A ~ 200 NM, 25 KHZ
ENV CAT. /A2E1/B/JY/EXXXXXZ/BZ/AZA
WT 4.7 LB S/N 33066
FCC ID AUL9UO PN622-6152
Rockwell International Corporation
Collins General Aviation Division
Cedar Rapids, IA 52498 USA Mfd Melbourne, FL

011

16 18
22 23 24
A B C

A #40

#40



MNE-CJU Maintenance Center(B03)

SERVICEABLE

MOLIT Certificate Number

☒ 2004-AMO-A01 (M&E)

☐ 2004-AMO-S02 (ASD)

Instance Number		Manufacturer		Preservation Maintenance		
				Complete Date YYYY-MM-DD	Due date YYYY-MM-DD	Inspector
Description VHF-22A TRANSCEIVER				YYYY-MM-DD	YYYY-MM-DD	
Part Number 622-6152-011		Storage Limit Control		YYYY-MM-DD	YYYY-MM-DD	
Serial Number 33066	Quantity - 1 -	Part Attribute		YYYY-MM-DD	YYYY-MM-DD	
Service Date YYYY-MM-DD 2020-12-11	TSO/CSO	☐ Life Limited Parts ☐ ESDS ☐ Hard Time Control ☐ CMP Chk Required		Hard Time Control Part Date Only Manufacture Date YYYY-MM-DD		
Technician [JS오정기] 2004065	RTS/Inspector			HYD Test Date YYYY-MM-DD	Restoration Date YYYY-MM-DD	
PO/Work Order No	Status/Work	Remarks				
Serviceable Removed From						
A/C Type(or NHA P/N) CTN-560	A/C No(or NHA S) 7501					
Position						