

Collins


VHF-22A

MOD
1
2
3
4
5
6
7
8
9
10
11
12

TRANSCEIVER, VHF COMM
TYPE NO. VHF-22A FAA TSO C38c, C37c
DO-160A 200 NM, 25 KHZ
ENV CAT. /A2E1/B/JY/EXXXXXZ/BZ/AZA
WT 4.7 LB S/N 32594
FCC ID A.JL9UQ PN622-6152 011
Rockwell International Corporation
Collins General Aviation Division
Cedar Rapids, IA 52498 USA M-1 Melbourne, FL

16
17
18
19
20
21
22
23
24
A
B
C

A 39



MNE-CJU Maintenance Center(B03)

SERVICEABLE

#39

MOLIT Certificate Number

2004-AMO-A01 (M&E)

2004-AMO-S02 (ASD)

Instance Number		Manufacturer		Preservation Maintenance		
Description				Complete Date	Due date	Inspector
VHF-22A TRANSCEIVER				YYYY-MM-DD	YYYY-MM-DD	
Part Number		Storage Limit Control		YYYY-MM-DD	YYYY-MM-DD	
622-6152-011						
Serial Number	Quantity	Part Attribute		YYYY-MM-DD	YYYY-MM-DD	
32594	- 1 -					
Service Date	TSO/CSO	<input type="checkbox"/> Life Limited Parts <input type="checkbox"/> ESDS <input type="checkbox"/> Hard Time Control <input type="checkbox"/> CMP Chk Required		Hard Time Control Part Date Only		
YYYY-MM-DD				Manufacture Date	HYD Test Date	Restoration Date
2020-12-11				YYYY-MM-DD	YYYY-MM-DD	YYYY-MM-DD
Technician	RTS/Inspector	Remarks				
JS오정기 2004065						
PO/Work Order No	Status/Work					
Serviceable Removed From						
A/C Type(or NHA P/N)		A/C No(or NHA S/N)				
CTN-560		7502				
Position						