

SA-0060

MAINTENANCE RELEASE

MAKE Collins MODEL Ind-42C
SERIAL NO. 7061 P/N 622-738-001
OWNER N6137A TOWNLEY MFG

The Aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service.

Pertinent details of the repair are on file at this agency under work order No. GSP-WO-2632

Date 12/16/2011 Stevens Aviation
Signed Jamie A. Oster R.S.# V125368K
LOC. GSP

COLLINS
CHITA SERVICE CENTER
2051 Airport Road
Wichita, KS 67209-1949
PHONE: (316) 677-4808
FAX: (316) 942-3843
michi_a@collins.rockwell.com