

CHERRY® Brand Aerospace Fasteners

DO NOT OPEN BAG UNTIL FASTENERS ARE TO BE USED

Contents may become contaminated or lose their lubricant,
which may affect installation performance.

**IMPORTANT: BLIND FASTENERS ARE NOT ALWAYS INTERCHANGEABLE WITH
NON-BLIND FASTENERS. CONSULT WITH THE AIRCRAFT ORIGINAL EQUIPMENT
MANUFACTURER FOR PROPER APPLICATION OF THIS PRODUCT.**

ACCEPT NO SUBSTITUTES™

P.O. 2028-00378

BACR15FR4B4R

FAA-TSO-C148

CR3243-4-04

FAA-TSO-C148

LOT # 86517278



Hole .143 .146

CHERRYMAX

Grip .188 .250

QTY



Sep 2005

100

ALSO IN FULL COMPLIANCE WITH THE
FOLLOWING NON-TSO PART NUMBER(S)

NAS9304B-4-04

S2456 4-4

NAS9304BNS-4-04

MBBN3012L3604

M7885/6-4-04

PAN3644-32-04

ASNA0078A404X

E2706288

TEXTRON Fastening Systems

Santa Ana Operations

1224 East Warner Avenue, Box 2157

Santa Ana, CA 92707-0157 U.S.A.

www.textronfasteningsystems.com/aerospace • phone: 714-545-5511

FSCM 11815