

DO NOT OPEN BAG UNTIL FASTENERS ARE TO BE USED
Fasteners may become contaminated or lose their lubricant, which
may affect their installation performance.



NAS 1739MW6-5
2010-00102

CR2538P-8-05	FAA-TSO-C148

LOT # 85780619



Hole .205 .209

Grip .251 .312

Qty.



100

FEB 00

CHERRYLOCK®

VISIT OUR WEB SITE
WWW.TAF.TEXTRON.COM

ALSO IN FULL COMPLIANCE WITH THE
FOLLOWING NON-TSO PART NUMBER(S)

NAS1739MW6-5

TEXTRON Aerospace Fasteners

A Division of Textron Inc.
1224 East Warner Ave., Box 2157
Santa Ana, CA 92707-0157
FSCM 11815