HONEYWELL INC.

DU-870

DISPLAY UNIT

PART NO. 7014300- 901 SN 98103874 WT 25.6 LB TSO C63c C113, SOFTWARE LVL2 D0-160C[A1F1]VBA(PBS)XXXXXXAZAZAVZKXX 28VDC

MOD

UVWYZ

BUS. & COMMUTER AVN SYS DIV PHOENIX AZ USA

Approving Civil Aviation Authority/Country: FAA/United States 2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG					3. Form Tracking Number: I REP-13190
Organization Name and Address INAir Aviation Services 8225 Country Club Place, Indianapolis, Indiana Certificate No. IOVR072L					5. Work Order/Contract/Invoice Number: I REP-13190
. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11 Status/Work:
1	DISPLAY UNIT	7014300-901	1	98103874	Repaired
2 REM	MARKS: Work complete.	Repaired, inspected and approved for return	to service.		
Certific		block 1 1/12 was carried out in accordance w.4563.	rith EASA PART145 an		raft component is considered ready for release to serve
Certific under l	es that the work specified in EASA approval number 145	block 11/12 was carried out in accordance w. 4563. Per EASA requirements for	FAA approved date, E. 14a. X Certifies and desc	i in respect to that work the airconcerning the decentive Decision 2007/004/R appearance of the decention of	popules. X Other regulation specified in Block 12 Block 12, the work identified in Block 11 d in accordance with Title 14. Code of Federal
Certific under l	es that the work specified in EASA approval number 145	block 11/12 was carried out in accordance w. 4563. Per EASA requirements for the state of the s	FAA approved date, E. 14a. X Certifies and desc	i in respect to that work the airconcective Decision2007/004/R ap 14 CFR 43.9 Return to Service that unless otherwise specified in bied in Block 12 was accomplishens, part 43 and in respect to that	pplies. X Other regulation specified in Block12
Certific under	es that the work specified in EASA approval number 145	block 11/12 was carried out in accordance w. 4563. Per EASA requirements for	FAA approved date, E. I4a. X Certifies and desc Regulati to service 14b. Aut	i in respect to that work the airconcective Decision2007/004/R ap 14 CFR 43.9 Return to Service that unless otherwise specified in bied in Block 12 was accomplishens, part 43 and in respect to that	popules. X Other regulation specified in Block 12 Block 12, the work identified in Block 11 d in accordance with Title 14. Code of Federal
Certific under l	es that the work specified in EASA approval number 145	block 11/12 was carried out in accordance w4563. Per EASA requirements for	FAA approved date, E. I4a. X Certifies and desc Regulati to service I4b. Aut Bra	in respect to that work the airconcentric decentive Decision2007/004/R application 14 CFR 43.9 Return to Service that unless otherwise specified in ibed in Block 12 was accomplished ins., part 43 and in respect to that we concentrate of the concentration of the	Deplies. X
Certific under	es that the work specified in EASA approval number 145	block 11/12 was carried out in accordance w4563. Per EASA requirements for	FAA approved date, E. 14a. X Certifies and desc Regulati to service 14b. Aut 14d. Nar Bra	1 in respect to that work the airconcecutive Decision2007/004/R application 14 CFR 43.9 Return to Service that unless otherwise specified in ibed in Block 12 was accomplished ins. part 43 and in respect to that was not included Signature:	Deplies. X