

MOD				DATA CONCENTRATOR UNIT							
8	4	9	6	TYPE NO. DCU-4000	FAA-PMA	31	32	33	34		
12	10	18	14	DO-160C ENV CAT	DO-178A LEVEL 1	35	36	37	38		
16	14	17	18	WT 17.8 LB	SN 2640	39	40	41	42		
19	20	21	22	COLLINS PN 622-9820- 010		43	44	45	46		
23	24	25	26	Rockwell Collins, Inc.		47	48	49	50		
27	28	29	30	Cedar Rapids, IA 52498 USA/Mfd Melbourne, FL		51	52	53	54		
						A	B	C	D		
						E	F	G	H		

Cert # WAIR890
200 Jim Davidson Drive • Sugar Land, TX 77498
(281) 565-9700 • Fax (281) 565-9824

Western Airways

-REPAIRABLE PART-

PART NAME DCU PART NO. 622-9820-010

AIRCRAFT N42WA SER. NO. 2640

POSITION #1 DATE 11/05/19

MECHANIC AA INSPECTOR _____

REASON FOR REMOVAL Oil temp readings miscompare/erratic

REMARKS _____

WA 161

Rev. Orig