



PROFESSIONAL

FAA Repair Station No. P81R813N
Titusville, FL 32780
407-267-1040
F/T

DATE: MOD

WORK ORDER: 16-27-22
56107



VP
IF SE
IS BRO

INDICATOR
FUEL FLOW



ORDER NO.

PART NO. 3571212-0053

18

26 VOLTS 400 Hz
BEECH 101-384009-1
THE BENDIX CORPORATION
SOUTH MONTROSE, PA.

