

**EXCITER, IGNITION**

TYPE **TGLN28**

PART NO. **10-381550-** SERIAL **9021805 C**

REV **A**

REPAIR STA. NO. **OTBR527K**

ID NO. TTA10-70625-100

**DUTY CYCLE  
CONTINUOUS  
REPLACEMENT  
PLATE**


Repaired/  
Overhauled by:



**THRUST TECH  
ACCESSORIES, INC.**

Orig. Mfred. By:  
UNISON INDUSTRIES 59501  
JACKSONVILLE, FL USA

1. Approving Civil Aviation Authority/Country: <b>FAA/UNITED STATES</b>	2. <b>AUTHORIZED RELEASE CERTIFICATE</b> FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number: <b>113170</b>
--	---	---

4. Organization Name and Address: <b>THRUST TECH ACCESSORIES, INC. dba: THRUST-TECH AVIATION</b> 6701B NW 12th Ave, Fort Lauderdale, FL 33309 USA p.954-984-0450 / f.954-984-0290 / info@thrusttech.com FAA Certificate No: OTBR527K	 <b>THRUST TECH</b> ACCESSORIES, INC.	5. Work Order/Contract/Invoice Number: <b>28114</b> <b>P00496</b>
--	---	---

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	IGNITION EXCITER	10-381550-22	1.00	9024R006	OVERHAULED

12. Remarks:

**WORK STATED IN BLOCK 11 WAS PERFORMED IN ACCORDANCE WITH FAA ACCEPTABLE DATA BELOW:**


Manual ID: DER TTA-R-010, Revision #: 0, Revision Date: 3/20/2009  
 Manual ID: DER TTA-R-018, Revision #: 0, Revision Date: 7/21/2009  
 Manual ID: DER TTA-R-019, Revision #: 0, Revision Date: 9/16/2009  
 Manual ID: DER TTA-RS-030, Revision #: 0, Revision Date: 4/9/2012  
 Manual ID: DER TTA-RS-039, Revision #: B, Revision Date: 3/23/2018  
 Manual ID: DER TTA-RS-042, Revision #: 1, Revision Date: 1/20/2012  
 Manual ID: DER TTA-RS-043, Revision #: 1, Revision Date: 3/23/2012  
 Manual ID: DER TTA-RS-044, Revision #: 0, Revision Date: 6/19/2012  
 Manual ID: DER TTA-RS-092, Revision #: 0, Revision Date: 9/17/2016  
 Manual ID: DER TTA-RS-105, Revision #: IR, Revision Date: 7/23/2015  
 Manual ID: DER TTA-RS-119, Revision #: IR, Revision Date: 1/31/2018  
 Manual ID: DER TTA-RS-126, Revision #: IR, Revision Date: 7/31/2017  
 Manual ID: SS TTA-SPE-096, Revision #: IR, Revision Date: 6/27/2024  
 Manual ID: SB 10-381550-2-49-11, Revision #: 0, Revision Date: 7/31/1994  
 Manual ID: 74-10-42, Revision #: 4, Revision Date: 1/3/2005  
 Manual ID: PMP-JP00414-2, Revision #: 2, Revision Date: 8/31/2009

**WORKORDER LISTED IN BLOCK 5 PRESCRIBING ACTUAL WORK PERFORMED IS ATTACHED.**

PUB ID: DER TTA-R-002 REV: 0 REV DATE: 10/19/06  
 PUB ID: DER TTA-R-008 REV: 1 REV DATE: 10/19/11

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the article is considered ready for release to service under EASA Part 145 approval number: EASA.145.5270.

13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12	14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.
--	---

13b. Authorized Signature:	13c. Approval Authorization No.:	14b. Authorized Signature: 	14c. Approval/Certificate No.: OTBR527K
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed): GARVIN MODESTE	14e. Date (dd/mmm/yyyy): 02/Jul/2025

**User/Installer Responsibilities**

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.