

DATE INST 9-30-04

SPERRY RAND

SF-50 G FLIGHT  
CONTROL SYSTEM  
PART NO. 2586687-902  
SERIAL NO. 0190990  
WT 24.9 TSO-C9c  
MOD ABC

SPERRY FLIGHT SYSTEMS DIVISION  
PHOENIX, ARIZONA

**PARTS IDENTIFICATION TAG**

Removed From H3

Description Roll Axis Computer

P/N 2586687-902

S/N 0190990

Notes \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Location in removal book. Page # \_\_\_\_\_ Item # \_\_\_\_\_

WO # \_\_\_\_\_

Date: 7/25/17

Removed By JC

AQP 180-1

HEADING SYNCHRONIZER  
PART NO. 2587829 - 1  
SERIAL NO. 120000  
SAE AS402A  
SPERRY PHOENIX CO.  
PHOENIX ARIZONA  
DIV. OF SPERRY RAND CORP.

SPERRY RAND  
PART NO. 2587829-1  
CHANGED TO MODIFICATION  
ABXDBXC II

SPERRY FLIGHT SYSTEMS DIVISION  
PHOENIX, ARIZONA

SERVO AMPLIFIER  
PART NO. 2587380 - 1  
SERIAL NO. 120000  
SAE AS402A  
SPERRY PHOENIX CO.  
PHOENIX ARIZONA  
DIV. OF SPERRY RAND CORP.

SPERRY RAND  
PART NO. 2587380-1  
CHANGED TO MODIFICATION  
ABXDBXC II

SPERRY FLIGHT SYSTEMS DIVISION  
PHOENIX, ARIZONA

LATERAL PATH  
COUPLER  
SP-50 FLIGHT  
CONTROL SYSTEM  
PART NO. 2586085 - 7  
SERIAL NO. 100116  
MOD. AXXXXGXXXXXXSLVW  
WT. \_\_\_\_\_  
SPERRY PHOENIX  
COMPANY  
DIV. OF SPERRY RAND CORP.

ROLL COMPUTER  
PART NO. 2587607 - 3  
SERIAL NO. 450002  
SAE AS402A  
SPERRY PHOENIX CO.  
PHOENIX ARIZONA  
DIV. OF SPERRY RAND CORP.

SPERRY RAND  
PART NO. 2587607-3  
CHANGED TO MODIFICATION  
ABXDBXC II

SPERRY FLIGHT SYSTEMS DIVISION  
PHOENIX, ARIZONA