



1. Approving national aviation authority/country Transport Canada		2.		3. Form Tracking No. 80693304		
4. Approved organization and address BOMBARDIER AEROSPACE		AUTHORIZED RELEASE CERTIFICATE TCCA 24-0078		5. Work Order/Contract/Invoice 6000240816		
Bombardier Inc. P.O. Box 6087, station Centre-Ville Montreal, Quebec, Canada, H3C 3G9.						
6. Item	7. Description	8. Part No.	9. Eligibility	10. Qty	11. Serial/Batch No.	12. Status/Work
000002	TUBE - FLUORESCENT	6845-245S	80% - 1A 10	30	N/A	Manufactured
000003	TUBE - FLUORESCENT	6845-355S	4	20	N/A	
000004	LINE ASSY - CAPILLARY	GC481-0100-15	1	11	N/A	
000005	POWER SUPPLY, FUSELAGE	8ES006794-22	4	2	S/N-1030694, 1047104	
000006	POWER SUPPLY, EMERGENCY LIGHTING	8ES409800-00	4	1	S/N:2987	
000006	POWER SUPPLY, EMERGENCY LIGHTING	8ES409800-00	4	1	S/N:2988	

1. This document does not constitute authority to install the part.
2. Where the installer works in accordance with the national regulations of an airworthiness authority other than the authority specified in block 1, the installer must ensure that his/her airworthiness authority accepts products or maintenance from the airworthiness authority specified in block 1.
3. Statements 14 and 19 do not constitute installation certification. In all cases, the aircraft technical record must contain an installation certification, issued in accordance with the national regulations of the state registry, before the aircraft may be flown.
*. Installer must crosscheck eligibility with approved data.