

HONEYWELL INC.

RM-850

RADIO MANAGEMENT UNIT

PART NO. 7012100- 825

S/N 99092575

DO-160B CAT A1F1/A/PKS/XXXXXXZBAZZ

WT 7.2 LB
MOD

DO-178A LEVEL 2

TSO C34d CLD;

C35d CLA; C36d;

C38c; C37c

200NM25KHz


C40b; C41d CLA;

C66b; C104 CLB;

D; C112 CLAO,

101, 010; C113;

C118; C119a



| | | | | |
|----|----|----|----|----|
| | | | | AN |
| | | | AS | AT |
| AU | AV | AW | AY | |
| AZ | BA | BB | BC | |

BUS. & COMMUTER
AVIATION SYS DIV
PHOENIX AZ USA

CAUTION
HIGH
VOLTAGE



N86MN

Hawker 800XP 258330 N86MN
Tulsa

W/O 553818/2

Beechcraft INC.

F.A.A. Air Agency Certificate No. HMGR732E

REPAIRABLE PART TAG

Part Name RMU RM-850 (pilot)

Part No. 7012100-825 Serial No. 99092575

Remarks: _____

Mechanic RF Date 11-16-15

Inspector _____ Date _____