



1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 8238774	
4. Organization Name and Address: Textron Aviation Inc. (PC4) Textron Aviation Inc. 1 Cessna Blvd, Wichita, KS 67215				5. Work Order/Contract/Invoice Number: 4777332			
6. Item: 10	7. Description: BOOT ASSEMBLY	8. Part Number: 101-120091-37	9. Quantity: 1	10. Serial Number: N/A	11. Status/Work: New		
12. Remarks: AUTHORIZED RELEASE DOCUMENT PO#: 205927							
13a. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.				14a. <input type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature: 		13c. Approval Authorization No.: PC4		14b. Authorized Signature: 		14c. Approval Certificate No.:	
13d. Name (Typed or Printed): JENNIFER FISHER		14d. Date (Typed or Printed): 27/Apr/2022		14e. Name (Typed or Printed): AJP LGE OKC		14f. Date (Typed or Printed):	
<p>User/Installer Responsibilities</p> <p>It is important to understand that the existence of this document alone does not automatically constitute an installation certification. Where the user/installer performs work in accordance with the national regulations of the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s) article(s) from the airworthiness authority of the country specified in Block 1.</p> <p>Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, repair records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft is flown.</p>							

Document Approved By: 
 APR 29 2022
 1331678
 PO#: