

Collins

HPU-74

HPU FLAG

EFD FLAG

35	36	37	38
39	40	41	42
43	44	45	46
47	48	49	50
51	52	53	54
A	B	C	D
E	F	G	H

TYPE NO. HPU-74 TSO C6c, C52a, C40b  
DO-160A ENV CAT. F2B/JY/XXXXXXA/BZ/AZA  
WT 4.5 LB S/N 493  
COLLINS PN 622-6198-002  
Collins Avionics Divisions/Rockwell International  
Cedar Rapids, IA 52498 USA/Mfd Melbourne, FL

MOD	1				
4	5	6			
7	8	9			
11	12	13	14		
15	16	17	18		
19	20	21	22		
23	24	25	26		
27	28	29	30		

HSI PROCESSOR UNIT

31	32	33	34
35	36	37	38
39	40	41	42
43	44	45	46
47	48	49	50
51	52	53	54
A	B	C	D
E	F	G	H

TYPE NO. HPU-74 TSO C6c, C52a, C40b  
DO-160A ENV CAT. F2B/JY/XXXXXXA/BZ/AZA  
WT 4.5 LB S/N 493  
COLLINS PN 622-6198-002  
Collins Avionics Divisions/Rockwell International  
Cedar Rapids, IA 52498 USA/Mfd Melbourne, FL