

# COCKPIT VOICE RECORDER MODEL A200S

PNR S200-0012-00  
SER 000113574  
MFR 06141  
DMF 012001



TSO-C123a  
ED-56A  
ARINC 757

## MODIFICATIONS

1  2  3  4 0 5 0 6 0 7 0  
8 0 9 0 10 0 11 0 12 0 13 0 14 0  
15 0 16 0 17 0 18 0 19 0 20 0 21 0

## PROGRAM REV

1 0 2 0 3  4 0 5 0 6 0 7 0  
8 0 9 0 10 0 11 0 12 0 13 0 14 0  
15 0 16 0 17 0 18 0 19 0 20 0 21 0





**communications**  
Sarasota, Florida, USA



UNDERWATER ACOUSTIC BEACON  
MODEL DK120/90  
DUKANE SEACOM, INC.  
Sarasota, FL 34243 USA  
TSO-C121b, TSO-C142a  
ETSO-C121b, ETSO-C142a

**WARNING:** DO NOT OPEN, DISASSEMBLE, CRUSH,  
PENETRATE, INCINERATE, OR EXPOSE TO TEMPERATURES ABOVE

1. Approving Civil Aviation Authority/Country: <b>FAA/UNITED STATES</b>		2. <b>AUTHORIZED RELEASE CERTIFICATE</b> FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: <b>1107234</b>	
4. Organization Name and Address:  <b>Velocity Aerospace, Inc.</b> 600 Radiator Rd, Suite 102 Indian Trail, NC 28079 Ph: (954)772-4559 FAA Repair Station No. WI4R623M				5. Work Order/Contract/Invoice Number: <b>04_289465 /</b> <b>P00736-1</b>		
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	SSCVR	S200-0012-00	1.00	000113574	INSPECTED	
12. Remarks: Full details of the work performed indicated in Block 11 are documented on W/O 04_289465  INSPECTED TO MFG SPECS Technical Data:23-70-03 Revision#: 5 Revision Date: 3/1/2005  Certifies work specified in Blocks 11/12 was carried out in accordance with EASA Part 145, and with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.4579.						
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12			14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval Authorization No.:	14b. Authorized Signature: 		14c. Approval/Certificate No.: <b>WI4R623M</b>	
13d. Name (Typed or Printed):		13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed): NATHANIEL HAUGEN		14e. Date (dd/mmm/yyyy): 19-Nov-2025	
<b>User/Installer Responsibilities</b>						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.  Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.  Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						