

O'Brien Enterprises

2420 E. 28th Street, Suite 2
Signal Hill, California 90755
Tel: 562-988-9546
Email: sobrienenterprises@gmail.com

WORK ORDER NO. **HY 28176**
D.O.T. #B528

HYDROSTATIC TEST FINDINGS AND COMPLETION REPORT

Customer Pius Parts Date Received 04MAY2026
Address Rockport TX Units Received this P.O. 1
P.O. # PO1051 Unit 1 of 1 Units. Page 1 of 2 Pages
Mfg. Part Number 212940-2 Assembly Serial # 10488
Other Part Number 9912103-3 Cylinder Serial # 83104 B1
Manufacturer: Valve P/N # _____
Kidde ☐ HTL/PacSci ☒ Scott ☐ Puritan ☐ B/E ☐ Tavco ☐ Av-Ox ☐ Sota ☐
Aerox ☐ Precise Flight ☐ ITT ☐ Other _____
Valve(s) Serial # _____
Description: O2 Cylinder ☐ N2 Cylinder ☒ Other _____

REASON FOR RETURN

Hydrostatic Test ☒ Other: _____
Repair ☐ _____
Recharge ☐ _____
Service Regulator ☐ _____

INITIAL INSPECTION

Date of Mfg: 11-2020 Size: 90 C.F. ☐ TEST PRESSURE 4800 P.S.I.
Last Hydro: 11-2020 C.I. ☒ Other Information: _____
DOT Rating: _____
8162-1850 ☐ Non-DOT Cylinder ☒ Full ☐
3AA1800 ☐ Other _____ Empty ☒
3HT1850 ☐
10945-1850 ☐
3AL _____

Parts Missing: None ☐ Safety Cap(s) ☐ Valve(s) ☐ Fittings ☒ 4 Other: _____
Additional Parts Received: None ☒ Safety Caps ☐ Strap/Clamp ☐ Mask ☐ Other: _____
Exterior Condition: Good ☐ Fair ☒ Poor ☐ Comments: _____
Interior Inspection: Pass ☒ Fail ☐ Hidden Damage: None ☒ Comments: _____

Repairable: Yes ☒ No ☐ BER/Scrap: Yes ☐ No ☒
Serviced per Mfg: HTL/PacSci ☒ Kidde ☐ DOT/CFR49 ☐ Other: _____
Serviced I.A.W. Customer Procedures Manual: Yes ☐ No ☒ Manual # 36-10-03 Rev. 11/03
Other: _____

CORRECTIVE ACTION

Hydrostatic Test ☒ Scope of Work: _____
Inspect Interior ☒ Repaired ☐ _____
Refinish Ext. ☐ Recharge ☐ _____
Wt. and/or Leak Test ☐ No Work Done ☐ _____
Inspect and Condemn ☐ _____