




Unitron LP  
10925 Miller Road  
Dallas, TX 75238



## Certificate of Conformance

Customer:

Pius Parts  
11 Bee Tree Cir  
Rockport TX 78382

Status:

Repaired

Product Type:

GPU

Customer Purchase Order:

Unitron Order Number: FX1300

Customer RMA Number: 49111

Unitron, LP / FoxCart GSE certifies that the items listed below have been repaired and inspected in accordance with all requirements called for in your Purchase Order listed above, and in accordance with all applicable Unitron design data and procedures. The items listed below have been repaired in the United States of America.

| Item | Part Number        | QTY | Description        | Serial Number |
|------|--------------------|-----|--------------------|---------------|
| 1    | Foxcart Model 1200 | 1   | Foxcart Model 1200 | 12085-A       |
|      |                    |     |                    |               |
|      |                    |     |                    |               |
|      |                    |     |                    |               |
|      |                    |     |                    |               |

Unitron test equipment used for product acceptance testing is traceable to the standards of ISO/IEC 17025:2005, ANSI/NCSL Z540-1-1994 & ANSI/NCSL Z540.3-2006 as applicable. Records are on file at the facilities of Unitron for your examination.

The Quality Management System of Unitron LP is certified to the requirements of ISO 9001:2015.

| Unitron LP Authorized Representative |                     |         |
|--------------------------------------|---------------------|---------|
| Printed Name:                        | Signature or Stamp: | Date:   |
| REGINA KEOGH                         | Regina R Keogh      | 6/20/24 |



7550  
Cir  
78382

Order  
FX00007  
FACTORY RE  
FACTORY RE  
Foxcart 12C




# FOX CART TEST DATA

10000 Miles Road, Dallas, TX 75228 • 1984  
(817) 465-8800



|             |         |                    |        |                 |            |                |  |
|-------------|---------|--------------------|--------|-----------------|------------|----------------|--|
| DATE        | 5/21/23 | MODEL #            | 1200   | DC CABLE LENGTH | 10         | AC RIPPLE      |  |
| JOB NUMBER  | 9911    | SERIAL #           | 120854 | AC CABLE LENGTH | 30         | AC PLUG        |  |
| SALES ORDER | F13300  | TEST INPUT VOLTAGE | 208    | AC CABLE TYPE   | 5 ft c gnd | 50 (60) 400 Hz |  |



TAP  
VOLTAGE  
26.72  
27.64  
28.56  
29.48  
30.40  
31.32  
32.24  
33.16

|                   |                                                               |                       |     |     |                         |    |
|-------------------|---------------------------------------------------------------|-----------------------|-----|-----|-------------------------|----|
| (circle one) NEW  | REPAIR                                                        | STRAPPING ON DELIVERY | 240 | WVC | ASSEMBLED / REPAIRED BY | 33 |
| INSPECTOR         | Signatures                                                    |                       |     |     |                         |    |
| REPAIR COMPLAINT: | input cable broke & shorted<br>input connector full of water. |                       |     |     |                         |    |

CORRECTIVE ACTION:  
(list all parts used on work, order)







