

AERO SKY
2030 First Avenue, Hangar 4
San Antonio International Airport
San Antonio, Texas 78216
FAA Approved Repair Station No. K07R556N

REJECTED PARTS TAG

Registration N14629 Work Order No. JS82012-C
Date MAY 13 2014
Manufacturer SECAW
Identification #2 ENG Fuel/oil Heat exchanger
Part Number 69-202-300-3 Serial Number 12364
Qty 1 TSO Location #2 ENG
Discrepancy 3 cracks on outside AND
on mating surfaces
Rejected by Inspector (Printed Name) _____
Signature _____