





Lucas Air Equipment
F8103
ELECTRIC PUMP
P/N
C11V00020
CODE 88 023 023 00
DATE 10-9-81
SN

WHEELER
CORPORATION
SPRING



CONSOLIDATED AIRCRAFT SUPPLY CO., INC.
55 RAYNOR AVE., RONKONKOMA, NY 11779

FAA REPAIR STATION #G11R167K
DATE 29/JAN/2025 JOB# 247189

COMPONENT TEARDOWN REPORT - FORM 261

Revision Date 04/25/14

NOMENCLATURE: PUMP, FUEL	WORK PERFORMED: OVERHAULED EVAL
PART NUMBER: C11VQ0020	CUSTOMER: PIUS PARTS
SERIAL NUMBER: 658	CUSTOMER P.O.#: P00117
AMEND./MOD. PLATE STATUS: N/A	MANUFACTURER: BRONZAVIA (GOODRICH)
REQUESTED/REQUIRED MODIFICATION: YES _____ NO <u>X</u>	REVISED PART #: N/A REVISED SERIAL #: N/A

AIRWORTHINESS DIRECTIVES - FAA AD: YES _____ (COMPLETE BLOCK 6) NO X EASA AD: YES _____ (COMPLETE BLOCK 6) NO X

1) RECEIVING REMARKS: (CUSTOMER INSTRUCTIONS, AIRCRAFT REMOVAL INFO, T.S.O. T.S.N.)

REPAIR REQUIRES OVERHAUL.

2) TEARDOWN REMARKS:

ALL PACKINGS AND BRUSHES ARE WORN. SEAL JETS MISSING. ARMATURE FAILED STATIC CHECKS REQUIRES REWIND. FILTER FAILED STATIC CHECKS. CLOGGING CAP HAS EXCESSIVE CORROSION.

3) REPAIR ACTION TAKEN:

NWA. CUSTOMER REJECTED JOB. LOOSELY ASSEMBLED.

4) INSPECTION REMARKS: (EXPLAIN P/N OR S/N CHANGES)

N.D.T. REQ'D.: YES _____ NO X

NWA.

ALL WORK DONE IN ACCORDANCE WITH: 28-21-71 REV 6 JUNE 15/07

5) SERVICE BULLETINS COMPLIED WITH: N/A

6) A.D. COMPLIED WITH THIS VISIT: A.D.# N/A

A.D. PREVIOUSLY COMPLIED WITH: A.D.# N/A

COMMENTS:

TECHNICIAN'S SIGNATURE

