

AERO SKY
2030 First Avenue, Hangar 4
San Antonio International Airport
San Antonio, Texas 78216
FAA Approved Repair Station No. KQ7R556N

PART I.D. TAG

Registration N306FA

Work Order No. FA40113-A

Date 9-19-23

Manufacturer MD-83

P/N M30903827

S/N 02110

Location Left engine Quantity 1

Removed For FOM

Initiated By: Eduardo Amador