

1. UNITED STATES

2. **FAA FORM 8130-3**
AIRWORTHINESS APPROVAL TAG
U.S. Department of Transportation
Federal Aviation Administration

3. System Tracking Print No.:
BN031398091021EC203

4. Organization
BFGoodrich Aerospace Component Overhaul & Repair
817 West Howard Lane
Austin, Texas 78753

(512) 251-3441 (FAX)
(512) 957-1274 (FAX)
FAA Repair Station No. UZ2R232L

5. Work Order, Contract, or Invoice Number
W.O. # **EC203**

12. Status/Work

6. Item	7. Description	8. Part Number	9. Qty.	10. Qty.	11. Serial/Batch Number	12. Status/Work
1	CONTROL HEAD	VC297	1		11011	REPAIR/BENCH CHECK

13. Remarks 1) Work order no. EC203

2) Item 1 was manufactured by

GABLES ENGINEERING

Indicates the actual work performed. All work was performed in accordance with FAA approved data.

Cust PO# 78A

REPLACED WINDOW SEAL, ALIGNED COUNTER ASSY AND LUBRICATED AS NEEDED,
CLEANED FRONT PANEL, TOUCH UP PAINT, PAINTED KNOBS, CLEANED WINDOW
INSIDE & OUT, UNIT CONFIGURED AS VC297-X-FW418, CHECK TEST IAW GABLES
SPEC

14. New ☐ Rebuilt ☐ Limited life parts must be accompanied by maintenance history including total time/total cycles/terms since new

15. Condition of parts at time of repair (overhaul, rebuild, etc.) identified above, except as otherwise specified to comply with FAA approved design data and airworthiness.

16. FAA Authorization No.:
17. Signature: *[Signature]*

18. Date: *[Signature]*

21. Certificate Number: UZ2R232L

22. Date: *[Signature]*

Eligibility: (Optional) Installer must cross check eligibility with applicable technical data.