



1. Approving Civil Aviation Authority/Country FAA/United States  2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG					3. Form Tracking Number:
k. Organization Name and Address: ICON AEROSPACE, LLC. 2617 EXECUTIVE POINT DR. MONROE, NC 28110			FAA Repair Station : 68IR700B EASA Reference : EASA.145.6295 Ph: 704-821-4266 Fax: 704-821-4286		5. Work Order/Contract/Invoice Number: W111947
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	TRANSFORMER	10212	1	W111947	INSPECTED/TESTED
3a. Certi	FULL DETAILS OF WORK ORDER NU	as that the work specified in blocks 11/12 was work, the component is considered ready for remanufactured in conformity to:  a condition for safe operation.	COMPLIANC N/A  COMPLIANC N/A  carried out in accordance with EAS elease to service under EASA Part  [4a. X] 14 CF  Certifies thi	A Part-145, and in respect 145 Approval Number EASA.145.624 R 43.9 Return to Service  X at unless otherwise specified at unles	
3b. Auth	orized Signature:	13c. Approval/Authori	ization:No.: 14b. Authorized	s)gnature:	14c. Approval/Certificate No. 68IR700B
3d, Name (Types or Printed): 13eDate (dd/mmm/yyyy		): 14d. Name (Typed or Printed) Agustin "Gus" Garcia		14e. Date (dd/mmm/yyyy) 25/Nov/2019	
		User/I	Installer Responsibilities		
		ce of this document alone does not automa cordance with the national regulations of ar nsures that his/her airworthiness authority			

NSN: 0052-00-012-9005