



SERVICEABLE/AS REMOVED

Reg. # & s/n 826 CP
Part Name base plateassy / exterior clat. hole
Part Manf. NA
Part Number 1217046-3
Serial Number NA
Removed By NA
Overhauled Function Test
Repaired Other

Serviceability Statement
Item identified above was serviceable at the time of Removal. It is the Responsibility of the Installing Mechanic or Institution to Verify Serviceability.

Maintenance Release
The aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repairs are on file at this repair station under Work Order # 6289

Inspected By [Signature]
For: NASHVILLE JET CENTER