

**SERVICEABLE/AS REMOVED**

Reg. # & S/N 826 CP

Part Name bis plate assy / interior door handle

Part Manf. NA

Part Number 1217046-3

Serial Number NA

Removed By NA

Overhauled  Function Test

Repaired  Other

Serviceability Statement

Item Identified above was serviceable at the time of Removal. It is the Responsibility of the Installing Mechanic or Institution to Verify Serviceability.

Maintenance Release

The aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repairs are on file at this repair station under Work Order # 6089

Inspected By D. C. Ellin  
For: NASHVILLE JET CENTER