



SERVICEABLE PART

Description: *CABIN TEMP CONT. BACK LIGHT OVERLAY*

Part/Model No.: *128-380012-5* Ser. No.: *—*

TSN: _____ CSN: _____ TSO: _____ CSO: _____

Description of Work:

RK201 REMOVED AS SERVICEABLE