

SERVICEABLE PART

Description: FWD CB Overlay 1 Ser. No.: NSN

Part/Model No.: 992-4225-611

TSN: REZEL MUCSN: 128-388049 -TSO:

CSO:

Description of Work:

*Removed In Serviceable Condition  
From M/C RK-201*

12104/13

CAT 003  
Rev. OR  
05/3/12

**MAINTENANCE RELEASE**

**Constant Aviation** / **Air Services**

CRS No. WC7R346J

Date 04/29/2014

The component on the reverse side was repaired and/or inspected in accordance with current Federal Aviation Regulations and is approved for return to service. Pertinent details of the repair are on file at this facility under

Work Order No. CC79-14/11.10  
R. Phillips

Technician: R. Phillips

Inspector: R. Phillips

A/C Reg

Pos.

Inst. By

**INSTALLATION DATA**

Model


Work Order

Date

A/C Time

Location

Ser. No.



CARE  
\$ 5,000

FLT IN  
PFD 1

RAYTHEON  
992-4225-611 REV N/R  
LSI  
95-4021-611 REV N/R  
06/04/98

