

**NORTON PERFORMANCE PLASTICS CORPORATION
COMPOSITES OPERATIONS**

FAA Approved Repair Station #OA1R367K
335 N. Diamond St., Ravenna, Ohio 44266
Ph: (216) 296-9948, Fax: (216) 296-8846

REPAIR REPORT

CUSTOMER: SABROLINER CUSTOMER P.O.#: 5074040
DESCRIPTION: SABROLINER Radome CUST. PART NO.: 3090X-10
PART S/N: 245
NORTON RO#: 94-414 NORTON ORDER#: B19682
NORTON P/N: 3090X-10

DESCRIPTION OF COMPLETED WORK

- I. TYPE OF REPAIR: Major: Repair Alteration (Form 337 Attached)
 Minor Repair
 Test Only
- II. COMPOSITE REPAIR: Repaired: Inner Skin Outer Skin Honeycomb
 Radome Cutoff and Repaired
 Radome Shell Replaced
 Edgeband Repaired
 Moisture Removed
 Other: Fill ALL Attached Holes
- III. PAINT/FINISH: Primer BMS 10-103 Grey Anti-Static
 Other: _____
- Topcoat: Caapcoat Erosion Paint Nose Full Radome
 Alumigrip Matterhorn White
 Jet Glo Matterhorn White
 Alumigrip Gloss Black
 Other: _____
- IV. MISCELLANEOUS: Lightning Diverters Repaired Replaced
 Erosion Boot Installed
- V. TRANSMISSION TEST: As Received: _____ % Average _____ % Minimum
 Outgoing: _____ % Average _____ % Minimum

VI. ADDITIONAL COMMENTS: _____

VII. APPROVAL

I certify that the repair work performed on this part was in accordance with the current Federal Aviation Regulations, manufacturers data, specifications and bulletins, or other technical data approved by the FAA.

FAA REPAIRMAN: Dwight Phillips Jr. CERTIFICATE NO.: 2429176
DATE: 9/15/94

Q-003
(8/93)

MAINTENANCE RELEASE

Norton Corp.
MANUFACTURER'S NAME
3090X-10

SABREliner Radome

UNIT NAME

245

MFR. PART NO.

SERIAL NO.

D. Phillips Sr.
INSPECTION CERTIFIED BY

TEST CERTIFIED BY

NORTON Performance Plastics Corporation

F.A.A. APPROVED REPAIR STATION No. OA1R367K

335 N. DIAMOND ST., RAVENNA, OHIO 44266

DESCRIPT OVERHAULED

P/N 3090X-10

CUST. P/N 3090X-10

S/N 245

R/O NO. 94-414

DATE Sept 1994

INSP 

NORTON

PERFORMANCE PLASTICS CORPORATION
COMPOSITES OPERATIONS

FAA APPROVED REPAIR STATION OA1R367K
335 N. DIAMOND STREET, RAVENNA, OHIO 44266
PHONE: 216-296-9948