




|  |                |   |                  |   |   |   |
|--|----------------|---|------------------|---|---|---|
| 1. UNITED STATES   |                | 2. <b>FAA FORM 8130-3</b><br>AIRWORTHINESS APPROVAL TAG<br>U.S. Department of Transportation<br>Federal Aviation Administration |                  |   | 3. System Tracking Ref. No.<br><br>42714500 |   |
| 4. Organization<br> <b>Kimhae Base</b><br><b>Korean Air Line, Kimhae International Airport</b><br><b>103 Ulman Ri, Daejeo 2 Dong, Gangseo Ku, Pusan, Korea</b>  |                | Repair Station<br><b>KALY462F</b>   |                  | 5. Work Order, Contract, or Invoice Number:<br><br>4 VK1  |   |   |
| 6. Item  | 7. Description | 8. Part Number  | 9. Eligibility * | 10. Quantity  | 11. Serial/Batch Number                     | 12. Status/Work                             |
| 1  | HF TXCVR       | 064101500   | CESSNA           | 1   | 6997  | Inspected                                   |
| 13. Remarks<br><br>I/A/W : Alliedsignal cmm 23-20-08<br>mech : RYU CH2 HYUN  |                |   |                  |   |   |   |
| Limited life parts must be accompanied by maintenance history including total time/total cycles/time since new.  |                |   |                  |   |   |   |
| 14. New<br>Newly Overhauled<br>Certifies that the new or newly overhauled part(s) identified above, except as otherwise specified in block 13 was(were) manufactured in accordance with FAA approved design data and airworthiness regulations.<br><b>NOTE</b> ; In case of parts to be exported, the special requirements of the importing country have been met.   |                |   |                  | 19. <b>Return to Service In Accordance with FAR 43.9</b><br>Certifies that the work specified in block 13(or attached) above was carried out in accordance with FAA airworthiness regulations and in respect to the work performed the part(s) is (are) approved for return to service. |   |   |
| 15. Signature  |                | 16. FAA Authorization No. :   |                  | 20. Authorized Signature :   |   | 21. Certificate Number :<br><b>KALY462F</b> |
| 17. Name (Typed or Printed) :  |                | 18. Date :  |                  | 22. Name (Typed or Printed) :    |   | 23. Date :<br>21 Feb 00                     |
| <b>Airworthiness Approval Tag</b><br><b>User/Installer Responsibilities</b><br>It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly.<br>Where the user/installer work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1 it is essential that the user/installer ensures that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.<br>Statements in block 14 and 19 do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown. |                |   |                  |   |   |   |

FAA Form 8130-3 (11-94)

\* (Optional) Installer must cross check eligibility with applicable technical data.

The FAA Forms 8130-3 and JAA Form one are equivalent. Other countries such as Canada also have equivalent acceptable documents.

CS Scanned with CamScanner

|   |  |           |   |   |                  |   |                   |
|---|--|-----------|---|---|------------------|---|-------------------|
| <b>SERVICEABLE</b>  | PRESERVATION MAINT.  |           |   | 에비품검정증명번호                                       |                  | TAG NO.                                   | P/ N              |
|   | COMP. DATA   | DUE DATE  | INSP                                    | 98SR-5144                                       |                  | 42714500                                  | * 064-1015-00     |
|   | DD MMM YY  | DD MMM YY | KAL 92                                  | 유효기간  |                  | S/ N                                      | MANUFACTURE       |
|   | 27 FEB 98  | N/A       | AVI 04                                  | 3000-11-17일까지                                   |                  | 6997                                      |                   |
|   | N/A  |           |   | 검사일   |                  |   |                   |
|   |  |           |   | 일월년   |                  |   |                   |
|   |  |           |   | 27 FEB 98                                       |                  |   |                   |
|   |  |           |   | KCAB APPROVED REPAIR STATION<br>NO. 1101 / 1102 |                  | DESCRIPTION<br><b>HF RECEIVER EXCITER</b> |                   |
|   | THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON THE FILE AT KOREAN AIR LINES UNDER. |           |   |   |                  | SVC. DATE                                 | A/C APPLICABILITY |
|   | WORK ORDER NO. 199902600   |           |   |   |                  | DD MMM YY                                 | MAINT. AUTH       |
| INSP. DATE 27 FEB 98 SIGNED J. Y. JEON (AUTHORIZED SIGNATURE)   |  |           |   |   | 18 FEB 98        | 8   |                   |
| FAA CERTIFICATED REPAIR STATION   |  |           |   |   | TSO / CSO        | TASK                                      |                   |
| <input type="checkbox"/> NO. KALY462F KIMHAE<br><input type="checkbox"/> NO. KAL2462F KIMPO<br><input type="checkbox"/> NO. KAL2462F BUCHEON<br>1 GONGHANG-DONG, KANGSEO-GU, SEOUL, KOREA |  |           |   |   | SLC              |   |                   |
| PART CHARACTER.   |  |           | NON-SERIALIZED HARD TIME CONT PART ONLY |   | TECHNICIAN       |   | INSP              |
| ESDS  | H.T CONT.  | S/N CONT. | MFG DATE                                | HYD TEST DATE                                   | RESTORATION DATE | OS탁유은 9007596                             | KAL 209           |
| Y   |  |           |   |   |                  | SERVICEABLE REMOVAL                       |                   |
|   |  |           |   |   | NHA P/N OR A/C   |   | S/N               |
|   |  |           |   |   | HL 7502          |   | POS               |
|   |  |           |   |   |                  |   | N/A               |

CS Scanned with CamScanner